



**GOVERNMENT OF KARNATAKA
PUBLIC WORKS DEPARTMENT**

No. AEE:No.1:PWD:ND:BS:2025-26/36

Office of the Assistant Executive Engineer,
No. 1, PWD South Subdivision,
K.R. Circle, Bengaluru.
Date: 19.04.2025

To:

The Principal

Hruthvi International School
H. Gollahalli Cross, Hemmigeपुरa,
Kengeri Main Road,
Bangalore - 560 060

Sir/Madam,


Sub: Renewal of No Objection Certificate (NOC) for Hruthvi International School building located at Survey No. 10/1, Somanahalli Village, Uttarahalli Hobli, Bangalore South Taluk

- Ref:**
1. Govt. Circular No. ED 43 PGC 2022, dated 18.05.2022
 2. Letter from the Commissioner, Public Department, Bangalore - Ref. No. 231:2018-19, dated 06.06.2022
 3. Request letter from Principal, Hruthvi International School, dated 27.03.2024
 4. This office letter No. 943/2023-24, dated 28.03.2024
 5. Request letter from Principal, Hruthvi International School, dated 03.04.2025

With reference to the above subject, Hruthvi International School building located at Survey No. 39/6, H. Gollahalli Cross, Hemmigeपुरa, Kengeri Hobli, Bangalore South Taluk, requires a **Safety Certificate** to be submitted to the Education Department. Hence the request letter cited at ref.(3) was submitted seeking the Safety Certificate. The said Certificate was already issued by this office for the year 2023-24 as cited at ref. (4). Further, as per ref. (5) cited above, have requested for the renewal of the **No Objection Certificate (NOC)**.

Based on the judgment given in **Civil Writ Petition No. 484/2004** by the Supreme Court, Executive Engineers of the Public Works Department are instructed to inspect school/college buildings and issue a "**Structurally Stable Certificate**". Also, as per the Government Circular cited at ref. (1), a **Structural Evaluation** of the existing constructed




Principal
Hruthvi International School

Aff. No. 831102, School Code : 46732
Address: H. Gollahalli Cross, Hemmigeपुरa - Kengeri,
Main Road, Bangalore - 560060.

building must be conducted and a certificate issued in accordance with **National Building Code standards**. Accordingly, a structural inspection of the proposed building has been carried out, and the following report is submitted.

The said building consists of ground, first, second, third, and fourth floors, constructed in the year **2018**. The building is equipped with toilet and drinking water facilities.

Furthermore, regarding the safety of the building, a report on the structural stability was submitted in **March 2024** by **Bangalore University, Department of Civil Engineering, UVCE, Jnanabharathi Campus, Bangalore - 560056**, through **Nishicon Infrastructures**. According to the inspection report submitted by them, the building was found to be **structurally sound**.

As per the Government Circular cited at ref. **(1) above**, to issue the **Building Safety Certificate**, an amount of **₹5,000/- (Rupees Five Thousand only)** was paid by **Hruthvi International School**, located at Survey No. 39/6, H. Gollahalli Cross, Hemmigeपुरa, Kengeri Hobli, Bangalore South Taluk, through **State Bank of India DD No: 058878**, dated **16-04-2025**.

Sl. No.	Approved Plan	Room Details
1	Ground + 4 Floors	a) Class Rooms - 42 b) Other Rooms - 08

The management of **Hruthvi International School** has reported in their application that the school building is constructed at Survey No. 39/6, H. Gollahalli Cross, Hemmigeपुरa, Kengeri Hobli, Bangalore South Taluk.

A physical inspection of the said building was conducted **in person on 05-04-2025**, and it was confirmed that there are **no modifications or additional floors** constructed. A **Non-Destructive Test (NDT)** on the structural integrity was conducted by **Nishicon Infrastructures, Bangalore**, and based on their report, the building is declared **structurally safe**.

Taking into account both the submitted test report and our personal inspection, we confirm that the school building located at Survey No. 39/6, H. Gollahalli Cross, Hemmigeपुरa, Kengeri Hobli, Bangalore South Taluk, consisting of **Ground + 4 Floors**, is **structurally stable for educational use for a period of 5 years**.

Note: A Fire Safety Certificate must be obtained separately from the Chief Fire Officer.

Yours faithfully

Sd/-

Assistant Executive Engineer,

No. 1, PWD South Subdivision,

Bangalore

Hruthvi International School

Aff. No. 831102, School Code : 46732
Address: H. Gollahalli Cross, Hemmigeपुरa - Kengeri
Main Road, Bangalore - 560060.

KARNATAKA STATE GOVT.
STOPPED ISSUING NOTARIAL STAMPS
HENCE NOT AFFIXED THE SAME



TESTED BY ME
05/04/2025
M. PRABHAKAR, B.A., LL.B.
ADVOCATE & NOTARY
GOVT. OF INDIA
No. 13, 3rd Cross,
Ard Nagar, BANGALORE-560018

Translated from
Kannada to English.
ಅನುವಾದಿತ
ಕನ್ನಡದಿಂದ
ಇಂಗ್ಲಿಷ್.